
N
Subsidence measuring line
Chaiwen river
Luli bridge
Downhill direction of working face
Advancing direction of working face
Estimated Surface crack caused by 1613working face
Estimated Surface crack caused by 1412working face
Surface crack caused by 1612 working face mining
Surface crack caused by 1411 working face mining
1613working face
1612working face (mined)
1611working face (mined)
1412 working face
1411 working face (mined)
1410 working face (mined)
Original village site of Mechangih
Grouting hole 10-1
Grouting hole 10-2
Grouting hole 10-3